Abstract

Method for coating a component

- Coatings that are applied to a component have to be removed again from certain areas using costly methods, because coating was not required in those areas. The subsequent removal of this layer can impair the component, for example in terms of its geometry.
- The inventive method for coating a component (1) uses a mask (7), which consists at least partially of a ceramic powder and can therefore easily be removed after the component (1) has been coated.

(Figure 2)

15